

#### **EnviroDIY Sensor Stations**

#### **Maintenance Quick Guide**



#### Stroud Center contacts:

- General:
  - David Bressler: <a href="mailto:dbressler@stroudcenter.org">dbressler@stroudcenter.org</a> 410-456-1071 (cell), 610-268-2153, ext. 312 (office)
- Technical:
  - Shannon Hicks: <u>shicks@stroudcenter.org</u>
     302-304-0957 (cell), 610-268-2153, ext. 267 (office);
  - Rachel Johnson: <u>rjohnson@stroudcenter.org</u>
     973-557-8995 (cell)

#### Take the following to site:

- EnviroDIY Field Visit Data Sheet
- Waders or knee boots
- Clipboard
- Pencils
- Brush
- Phone or watch
- Other supplementary items
  - Loppers/clippers
  - Camera
  - First Aid kit



# At the site do the following:

- 1. Fill in all header information on Field Visit Data sheet (see A, p. 9).
- Inspect site and sensors and take photos for before/after perspective (when appropriate).
- 3. Clean sensors (see following Step 3 details) and record on data sheet (see B, p. 9).
- 4. Remove debris and vegetation from around logger and solar panel.
- 5. Complete Sensor Station Maintenance section on data sheet (see C, p. 10).
- Complete General Notes section on data sheet (see A, p. 9).
- Take a strategic pause before leaving site.



# At home/office do the following:

1. Enter Field Visit Data sheet into online form:

https://wikiwatershed.org/drwi/
(password: drwi).

- 2. Store hard copy data sheet in secure location.
- Communicate with station owner and Stroud about any issues.



Use the soft long white bristles to remove debris from the entire sensor bundle.








The white disc ceramic coated pressure transducer can be easily damaged.

\*Do not touch it with anything when you are cleaning the sensor. •








Use the soft white bristles or Q-tip to gently clean the four screw heads (conductivity measured here).







Use the stiff gray bristles and/or your finger to clean the turbidity sensor "eye".









#### EnviroDIY Field Visit Data

WATER RESEARCH CENTER Enter all data online: wikiwatershed.org/drwi; password: drwi

LoggerID:	LoggerID:			
Location:	Location:			
Date:	Arrival Time: AM	PM? *EST/EDT?		
		tern Daylight Time		
	Vater Clarity (Clear, Cloudy, Muddy):			
antina Dhatan fa		Cook ZDV)		
tation Photos to	older ( <u>nttp://bit.ly/2</u>	SmnZBK)		
uenc . w sekly or biwee	kly; monthly if only CTD sens	or)		
A W/PM? ES	T/EDT? *Clean >5 min. be	efore grab sampling		
curves, collect when wat	er is nign/turbia or nigner than i	normai conauctivity)		
Time collecte	ed (to minute): AN	N/PM? EST/EDT?		
Volume:				
Volume:	d:			
-	d:			
Date Shippe	d: AB RESULTS ( <i>Complete in fie</i>			
Date Shippe		eld or office)		
Date Shipper Notes:	AB RESULTS (Complete in fie	eld or office) Always EST		
Date Shipped Notes:  VITH GRAB SAMPLE L.  Time (military):  Time (military):  og curve development.  npleted in field (by acc	AB RESULTS ( <i>Complete in fie</i> Not applicable	Always EST Always EST d and Turb data at the (online or down-		
Date Shipped Notes:  VITH GRAB SAMPLE L.  Time (military):  Time (military):  ag curve development.  Inpleted in field (by accoresults from Stroud Ce	AB RESULTS (Complete in fie  Not applicable  Not applicable  Record sensor station Concessing online data) or in office	Always EST Always EST Always EST d and Turb data at ce (online or down- cample).		
Date Shipped Notes:  VITH GRAB SAMPLE L.  Time (military):  Time (military):  ag curve development.  Inpleted in field (by accoresults from Stroud Ce	AB RESULTS (Complete in fie Not applicable Not applicable Record sensor station Concessing online data) or in officenter (or lab that processed s	Always EST Always EST Always EST d and Turb data at ce (online or down- cample).		
Date Shipped Notes:  VITH GRAB SAMPLE L.  Time (military):  Time (military):  og curve development.  onpleted in field (by accoresults from Stroud Ce	AB RESULTS (Complete in fie Not applicable Not applicable Record sensor station Conductoring online data) or in officenter (or lab that processed states)	Always EST Always EST d and Turb data at ce (online or down- sample).		
Date Shipped Notes:  VITH GRAB SAMPLE L.  Time (military):  Time (military):  ag curve development.  appleted in field (by accresults from Stroud Cellar  A (Rec frequency: qualime:	AB RESULTS (Complete in fie Not applicable Not applicable Record sensor station Conductoring online data) or in officenter (or lab that processed stately and/or more frequently AM/PM?	Always EST Always EST d and Turb data at the (online or downsample).  as needed) EST/EDT?		
	Location:  Date:  *EST=Easter (Daylight Saw Vater Clarity  tation Photos for weekly or biweek AM/PM? ES	Location:  Date: Arrival Time: AM  *EST=Eastern Standard Time; EDT=East (Daylight Savings)  Vater Clarity (Clear, Cloudy, Muddy):  Vater Clarity (Clear, Cloudy, Muddy):  **Polyment Clarity (Matter Clarity (Clear, Cloudy, Muddy):  **Polyment Clear Cloudy (Matter Clarity (Clear, Cloudy, Muddy):  **Polyment Clear		

WATER RESEARCH CENTER

a - Staff Gauge Height and Sensor Station Water Depth readings should be from about the same time (+/- 5 minutes).

b - Use metric ruler to measure from pressure transducer (white disc in CTD sensor) to water surface. Note - this depth measure may be slightly different from the sensor-measured depth but should be consistent over time.

QUALITY CON	ITROL - CHEMISTR	Y DATA (Rec	freque	ency: que	arterly and/or mo	re freque	ntly as ne	eded)
Parameter	QC Hand-held Meter Result	QC Time	QC A	M/PM?	QC EST/EDT?	Sensor Result	Station	Sensor Station- Time (Military, EST)
Conductivity (u\$/cm):			AM	I/PM	EST/EDT			
Temperature (degC):			AN	I/PM	EST/EDT			
Turbidity (NTU):			AN	I/PM	EST/EDT			
Dissolved Oxygen (mg/l	_):		AN	I/PM	EST/EDT			
	QUALITY CON	TROL CHEM	IISTRY	FIELD N	METER INFORMA	TION		
Parameter F	Field Meter Brand/	Model/Seria	al#or	unique	ID Meter cali	brated?	Standa	rd Calibration
Conductivity (uS/cm):					Yes/I	No		
Temperature (degC):					Yes/I	No		
Turbidity (NTU):	rurbidity (NTU): Yes/No							
Dissolved Oxygen (mg/	Dissolved Oxygen (mg/L): Yes/No							
	s	ENSOR STA	TION N	MAINTE	NANCE			
Sensors Submerged? Yes/No If no or partially, describe in Notes.			Notes (Describe specific sensor station management actions and any other issues):					
Location of Sensors Chalf yes, explain in notes. before changing location of	*Please consult Str	oud Center						
Retrieved Memory Card' (Rec frequency for QC: quif not online)		veekly-mont	hly					
Changed Batteries? Yes	/No							
Cleaned Solar Panel? Ye	es/No							
Other sensor station ma (If Yes, describe in Note	interior record	0						
OTHER	R IN-SITU PARAMET	ERS (e.g., Ni	trate, P	hospha	te, Chloride, pH, [	Dissolved	Oxygen)	
Parameter	Res	sult			Brand/Model			
OTHER INFORMATION								
Field Duplicate Taken of	Grab Sample? Ye	es/No	F	Flow Measurement w/ Neutrally Buoyant Object? Yes/No				
Performed Cross Section Survey? Yes/No		F	Flow Measurement w/ another method? Yes/No					
Flow Measurement w/ Flow Meter? Yes/No		- If	If Yes, explain in Notes					

